


CORNER RECORDDocument Number CR 9827City of OAKLANDCounty of ALAMEDA, CaliforniaBrief Legal Description MONUMENT WELL WITH COMPROMISED CORE LOCATED WITHIN THE INTERSECTION OF FRUITVALE AVENUE AND DAVIS STREET.**CORNER RECORD**Government Corner ☐Meander ☐Rancho ☐Date of Survey 2/10/17Control ☒Property ☐Other ☐**COORDINATES**
(Optional)

N. _____

E. _____

Zone _____ Datum _____


Elev. _____

Corner — Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND MONUMENT WELL LOCATED WITHIN THE INTERSECTION OFFRUITVALE AVENUE AND DAVIS STREET.CONCRETE CORE DAMAGED. NO PIN FOUND. MEASUREMENT TAKEN AT CENTER OF CONCRETE.THIS POINT WAS REFERENCED PRIOR TO A CONSTRUCTION PROJECT IN THE VICINITY.

A description of the physical condition of the monument as found and as set or reset: _____

FOUND AND SET POINTS AS SHOWN ON PAGE 2.THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTATION.NO CLAIM IS MADE AS TO THE RELATIONSHIP OF THE POINTS OR LINES SHOWN HEREON TOTRUE BOUNDARY LOCATIONS.**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on FEBRUARY 22, 2017.Signed Scott V. Cunha L.S. Number LS 8525
SCOTT V. CUNHA**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received 20 MARCH 2017 and examined and filed 12 JUNE 2017.Signed Michael Rubner Title COUNTY SURVEYOR**County Surveyor's Comment** _____

SCALE: 1"=30'

LEGEND

- FOUND MONUMENT WELL WITH DAMAGED CONCRETE CORE.
NO PIN FOUND. MEASUREMENT TAKEN AT CENTER OF CONCRETE.
- ⊗ SET CUT CROSS IN WALK
- ✕ SET CUT CROSS IN CURB
- ⊗ SET MAG AND SHINER
- SET REBAR & CAP STAMPED "CEI RP"
- AA##A# ALAMEDA COUNTY MONUMENT ID
- 19592 REFERENCE STREET ADDRESS

